


User's Guide

**EXTECH**<sup>®</sup>  
INSTRUMENTS

A FLIR COMPANY

# Digital Force Gauge

Models 475040 and 475044




## Introduction

Congratulations on your purchase of Extech's Digital Force Gauge. This professional meter, with proper care, will provide years of safe reliable service. Measure Tension or Compression (Push or Pull) to 5kg (475040) or 20kg (475044), reversible display indicates readings in grams, ounces, or newtons. This meter offers Peak Hold and a Zero function.

## Meter Description

1. Universal sensing head
2. LCD Display
3. Fast response indicator
4. FAST / SLOW response selection
5. LCD reverse display button
6. Zero/Tare button
7. Units select switch
8. Mounting Holes (on rear)
9. Battery compartment cover (on rear)
10. Flat Head adapter
11. Cone adapter
12. Chisel adapter
13. Hook adapter
14. 5" (120mm) extension rod
15. OFF/ON/PEAK HOLD button



## Operation

### Preparation for Measurement

1. The 475044 or 474040 automatically determines TENSION or COMPRESSION (Push or Pull) force during use. Compression displays as a negative value and Tension displays as a positive value.
2. Select units of measure (grams/kilograms, ounces/pounds, or newtons) via the units select button.
3. Attach the desired adapter (tension – hook; compression.- flat, cone or chisel head) to the Universal Sensing Head.
4. Select FAST or SLOW response. The FAST setting permits the capture of fast measurement changes and the SLOW setting provides an averaged reading display.
5. Zero the display before each measurement via the Zero button.

**Note:** The sensing head with adapter must be in line with the object being measured. Avoid rotating the sensing head. Refer to the figure below.

**Figure 1 – Correct and Incorrect Angles of Measurement**



## Normal Measurement Mode

1. Slide the POWER switch to the ON position. Reverse the LCD display if desired via the Reverse key.
2. Zero the meter before each measurement.
3. Touch the adapter to the object being measured in a straight line. Refer to Fig.1.
4. Begin measurement by applying force (Push or Pull). Read the LCD display.
5. After completing the measurement, the display will indicate "0.00" if the position and angle of the Force Gauge have not changed.
6. If the position or angle of the Force Gauge changes during a measurement, the display may show one of the following:
  - a) The display overranges because the initial force of the transducer **decreases** due to a change in the position or angle of the Gauge after measurement.
  - b) The display indicates any value such as "12", "25", etc. This occurs because the initial force of the transducer **increases** due to a change in the position or angle of the Gauge after measurement.

**Note:** Be sure to press "ZERO" before taking any new measurements.

## Peak Load Measurement

1. Slide the POWER switch to the PEAK position...
2. Touch the adapter to the object being measured in a straight line, refer to Fig. 1.
3. Zero the meter before each measurement.
4. Begin measurement by applying force (pull or push). The LCD will display the peak value, which is the highest reading encountered.
5. After completing the measurement, the display will hold the peak load value if the position and angle of the Force Gauge have not changed.
6. After completing the measurement, the display will overrange if the position or angle of the Force Gauge has changed. This occurs because the initial force of the transducer **decreases** due to a change in the position or angle of the Gauge after measurement.

**Note:** Be sure to press "ZERO" before taking any new measurements.

## Fast/Slow selection

Press the FAST/SLOW key to select the desired display update rate. The "((●))" symbol will appear in the display when FAST is selected.

## Mounting

For best results, mount the Digital Force Gauge to a test stand. Mounting holes are provided on the rear of the meter.

## Maintenance

### Battery Replacement

The low battery indication appears as a "LO" on the display when battery voltage is less than 6.8V. To replace the battery:

1. Remove the two screws from the battery compartment cover.
2. Lift off the battery cover.
3. Replace with 6x 1.5V AA (UM-3) batteries. Observe polarity carefully.
4. Replace compartment cover and screws.



You, as the end user, are legally bound (**EU Battery ordinance**) to return all used batteries, **disposal in the household garbage is prohibited!** You can hand over your used batteries / accumulators at collection points in your community or wherever batteries / accumulators are sold!

**Disposal:** Follow the valid legal stipulations in respect of the disposal of the device at the end of its lifecycle

## Specifications

	475044	475040
Range	44 lbs, 20kg, 196 Newtons	176oz, 5000g, 49 Newtons
Accuracy (23°C)	±(0.5%rdg + 2 digits)	± (0.4%rdg + 1 digit)
Resolution	0.01lbs, 0.01kg, 0.05 Newtons	0.05oz, 1g, 0.01 Newtons
Overload Capacity	30kg	10kg
Circuit	Custom LSI microprocessor circuit	
Zero adjust	Button for Peak Hold and normal display zero	
Display	5 digits, 10 mm (0.4") LCD display	
Update Rate	Fast mode 0.2 secs; Slow mode 0.6 secs.	
Overrange Indicator	Displays "-----"	
Zero Control	Maximum capacity	
Full Scale Deflection	2.00mm	
Transducer type	Load cell	
Peak Hold	Freezes Max reading on display	
Operating Temperature	0 °C to 50 °C (32 °F to 122 °F).	
Operating RH	Max. 80% RH.	
Power Supply	6x 1.5V AA (UM-3) size battery or DC 9V adapter (not included)	
Weight	551g / 1.2 lbs	
Size	227 x 83 x 39 mm (8.9 x 3.3 x 1.5")	
Mounting Holes	Located on rear of gauge	
Accessories	Tension adapter (hook), compression adapters (flat, cone, and chisel), 5" extension rod, 6 x 1.5V AA batteries, case	

Copyright © 2010 Extech Instruments Corporation (a FLIR company)  
All rights reserved including the right of reproduction in whole or in part in any form